

Business:	Canberra Building Inspec	tions Fast and Professional	ABN: 32524279672
	info@canberrainspections		
Registered Inspector:	-	045 2233 863	
9			
Inspection Date:			
Client:			
Contact:			
	Sample Papert		
	Sample Report		
Suburb:			
The following inspection report is o	lesigned as a statement of the c	ondition of said property at the time o	f the inspection.
The inspector is not obligated or qu	ualified to give legal advice to an	y client as a part of this inspection.	
		nt directly to determine any remedies	or
expectations that may form part of		•	
Depending on the clauses included	d in the "offer and acceptance" th	ne vendor may not be obligated to ma	ke good some
or all of the issues discovered in th	nis report. This is not a termite/ p	est inspection report.	
		ance and accurately follow the require	ements of the
contract within the designated requ	iired time frames where significa	ant defects are to be reported to the ve	endor.
A PrePurchas	e Building report is compliant	with Australian Standards 4943.1-	2007
Abbreviations:			
LV low voltage	NW north west	GPO general power outlet	
RHS right hand side	SE south east	NE north east	
LHS left hand side	SW south west	WIR walk in robe	
WC water closet (toilet)	GF ground floor	cnr corner	
HWU hot water unit	FF first floor		
Access restrictions			
Did any of the below liste	ed items limit access to the	e property? Y or N	
<b>-</b>			
Furniture in the l		Y	
	holes to roof space.	N	
Insulation prese	•	Y	
	ulation will partially affect visibilit	y of ceiling joists	
Type of insulation:	Batts		
Additional types:	tin n in manf and a	V	
	ucting in roof space.	Y	
	op of roof limited by exces		
	ss to subfloor areas- Timb		
Locked doors to	store rooms/ sheds.	N	

Address: Sample Report Suburb: Macgregor

## **Significant Defects Summary**

### Action may be enforceable under a significant defect clause on the following items:

1 An extreme fire hazard is present in the roof around the flume vent from the wood fire. Ash and burn marks are present on the ceiling and battens in the region. The fire should be either replaced with a gas unit or cleanly connect to the outside air without any gaps that could allow embers to enter the roof cavity. The home would very likely have burned if it not for the fact that the roof frame is a steel truss.







#### Comments:

No significant defects were found during the inspection.

**End Of Significant Defect Report Summary** 

Address: Sample Report Suburb: Macgregor

### **Maintenance Report Summary**

### The following items are not enforceable unless specified:

- 1 It is advisable to renew the termiticide chemical perimeter barrier to prevent termite infestation.
- 2 It is advisable to install over flow pops in the gutters where water stains are present in the eaves.
- 3 It is advisable to keep the gutters and flashings clean and free from leaves and debris.
- **4** A drummy wall tile is present above the ensuite shower recess which may require some maintenance in the future
- **5** A crack is present along a join in the garage ceiling. This is due to the movement in the roof trusses. It is advisable to have this retaped and repaired, however, it is not a significant defect.
- **6** The pool fenccing requires self closing gates to comply with council regulations.
- **7** The eaves are loose along the right side of the home and should be reclipped back into the fascia to prevent collapse. This is not a significant defect. This is caused by rainwater overflowing into the eaves.
- **8** It is advisable to connect all downpipes to soak wells to divert water away from the footings to prevent subsidence and possible attraction of termites to moist ground.
- 9 The dog has damaged the shopper and laundry doors.
- **10** It is advisable to paint unpainted doors to preserve them.
- 11 Moisture ingress is present behind the bathroom shower wall. The reading is 45/100 which is approaching the damp level. The grout and water membrane should be repaired as normal maintenance here.
- **12** Moderate cornice cracking has occured around the home due to movement in the steel trusses. This should be repaired as normal cosmetic maintenance.

#### **End Of Maintenance Report Summary**

## **REI Regulations Summary**

### These items are enforceable under REI regulations:

- 1 Hard wired smoke detectors appear to be installed as required.
- 2 Two RCDs are installed in the meter box.

Note- The building inspector is not a licensed electrician. These comments are based on a visual inspection only. A safety inspection by a licensed electrician is recommended to ensure that the home is compliant with all safety regulations.

#### **End Of REI Regulations Summary**

Address:
Suburb:

Faulty Fixtures & Fittings Summary
Faulty Fixtures and Fittings (enforceable under most fixtures and fittings warranty clauses)  Any missing light globes that are identified in item 53 on the checklist should be rechecked at the final inspection to ensure that no significant electrical fault is present here.
1 The air conditioner is not in good working order.
2 The pool is not clean; the equipment should be tested to ensure that it is in good working order.

**End Of Fixtures & Fittings Summary** 

# **Structural Checklist**

Refer to Summary notes

Any item marked with an R will have a corresponding note in the relevant summary section of this report. R

	<u>ternal</u>	OK	No significant is	ssue
	tside of Roof  Overall roof cover condition acceptable.	N/A	Not Applicable	ОК
	·			
2	Visible cracks to roof tiles exceeding tolerance.		(tiled roof only)	OK
3	Visible cracking to flexipointing exceeding toler	ance.	(tilled roof only)	OK
4	Sags or bows in any plane of roof causing struc	ctural conce	ern.	OK
5	Excessive rusting of flashings causing significa	ınt leaks.		OK
6	Gutters generally functional. Excessive rust or	leaks?		OK
7	Significant water backflow leaks evident in eave	es.		R
	ter Box Termite perimeter barrier treatment within warr	anty.		R
9	Access to live mains adequately covered.			OK
10	2 x Electrical RCD safety switches installed in r	meter box.		RRE
11	Any isolated or danger tagged circuits.			OK
Ext	ternal Walls & Perimeter			
	Any Horizontal cracking which exceeds normal	settlement	cracks.	OK
13	Any Vertical cracking which exceeds normal se	ettlement cr	acks.	OK
14	Visual evidence of rising damp in the bottom 40	00mm of th	e walls.	OK
15	Asbestos may be present but not necessarily linfollowing areas:	mited to the	<del>)</del>	OK
16	Any significantly loose brickwork or soft mortar.			OK
17	Steps to outside of home in good condition and	d safe.		OK
18	All visible waste pipes connected to drains.			OK
19	Garage ceiling lining in good condition			OK
Fo	otings/ Foundations			
	Cracks visible in concrete footings.			OK
21	Sides of footings fully covered beneath soil leve	el.		OK
Pe	rgolas			
	Any timbers rotten or damaged beyond safe tol	lerances.		OK
23	Fixing of posts to ground creating a termite bar	rier.		ОК

Retaining Walls	
24 Retaining wall construction acceptable.	OK
25 Significant horizontal or vertical cracks in retaining walls.	ОК
26 Loose Brickwork present in retaining walls.	OK
27 Soft mortar or limestone resulting from insufficient tanking.	OK
28 Rotten stumps, beams or sleepers in retaining walls.	OK
Interior	
Ceilings 29 Popped screws or degraded straps causing sagging.	R
30 Sagging to ceilings causing structural concern.	R
31 Cracks along ceiling joins beyond acceptable tolerances.	OK
32 Cornice cracking exceeding normal settlement expectations.	OK
33 Evidence of significant water leaks in ceilings.	OK
34 Severe mould or water damage to wet areas.	OK
35 Hard wired or equivalent smoke detectors near all bedrooms.	R REI
Internal Walls 36 Any cracking which exceeds normal settlement cracks.	ОК
	OK R 30-50/100 Normal
36 Any cracking which exceeds normal settlement cracks.	
<ul><li>36 Any cracking which exceeds normal settlement cracks.</li><li>37 Moisture reading behind shower recess walls</li></ul>	R 30-50/100 Normal
<ul><li>36 Any cracking which exceeds normal settlement cracks.</li><li>37 Moisture reading behind shower recess walls</li><li>38 Any evidence of significant moisture barrier issues in the plaster.</li></ul>	R 30-50/100 Normal
<ul> <li>36 Any cracking which exceeds normal settlement cracks.</li> <li>37 Moisture reading behind shower recess walls</li> <li>38 Any evidence of significant moisture barrier issues in the plaster.</li> <li>Internal Floors</li> </ul>	R 30-50/100 Normal
<ul> <li>36 Any cracking which exceeds normal settlement cracks.</li> <li>37 Moisture reading behind shower recess walls</li> <li>38 Any evidence of significant moisture barrier issues in the plaster.</li> <li>Internal Floors</li> <li>39 Cracks to ground slabs exceeding normal limitations.</li> </ul>	R 30-50/100 Normal OK OK
<ul> <li>36 Any cracking which exceeds normal settlement cracks.</li> <li>37 Moisture reading behind shower recess walls</li> <li>38 Any evidence of significant moisture barrier issues in the plaster.</li> <li>Internal Floors</li> <li>39 Cracks to ground slabs exceeding normal limitations.</li> <li>40 Condition of timber floor boards (if applicable)</li> </ul>	R 30-50/100 Normal OK OK N/A
<ul> <li>36 Any cracking which exceeds normal settlement cracks.</li> <li>37 Moisture reading behind shower recess walls</li> <li>38 Any evidence of significant moisture barrier issues in the plaster.</li> <li>Internal Floors</li> <li>39 Cracks to ground slabs exceeding normal limitations.</li> <li>40 Condition of timber floor boards (if applicable)</li> <li>41 Sufficient access panels available to sub floors (if applicable)</li> </ul>	R 30-50/100 Normal OK OK N/A
36 Any cracking which exceeds normal settlement cracks.  37 Moisture reading behind shower recess walls  38 Any evidence of significant moisture barrier issues in the plaster.  Internal Floors  39 Cracks to ground slabs exceeding normal limitations.  40 Condition of timber floor boards (if applicable)  41 Sufficient access panels available to sub floors (if applicable)  Roof Space	R 30-50/100 Normal OK OK N/A N/A
<ul> <li>36 Any cracking which exceeds normal settlement cracks.</li> <li>37 Moisture reading behind shower recess walls</li> <li>38 Any evidence of significant moisture barrier issues in the plaster.</li> <li>Internal Floors</li> <li>39 Cracks to ground slabs exceeding normal limitations.</li> <li>40 Condition of timber floor boards (if applicable)</li> <li>41 Sufficient access panels available to sub floors (if applicable)</li> <li>Roof Space</li> <li>42 Any significant gaps between structural members due to sagging.</li> </ul>	R   30-50/100 Normal   OK   N/A   N/A   OK
36 Any cracking which exceeds normal settlement cracks.  37 Moisture reading behind shower recess walls  38 Any evidence of significant moisture barrier issues in the plaster.  Internal Floors  39 Cracks to ground slabs exceeding normal limitations.  40 Condition of timber floor boards (if applicable)  41 Sufficient access panels available to sub floors (if applicable)  Roof Space  42 Any significant gaps between structural members due to sagging.  43 Unsound modifications done to roof/load bearing walls removed.	R   30-50/100 Normal   OK   OK   N/A   N/A   OK   OK   OK   OK   OK   OK   OK   O
<ul> <li>36 Any cracking which exceeds normal settlement cracks.</li> <li>37 Moisture reading behind shower recess walls</li> <li>38 Any evidence of significant moisture barrier issues in the plaster.</li> <li>Internal Floors</li> <li>39 Cracks to ground slabs exceeding normal limitations.</li> <li>40 Condition of timber floor boards (if applicable)</li> <li>41 Sufficient access panels available to sub floors (if applicable)</li> <li>Roof Space</li> <li>42 Any significant gaps between structural members due to sagging.</li> <li>43 Unsound modifications done to roof/load bearing walls removed.</li> <li>44 Lateral shift in hangers or strutting beams.</li> </ul>	R   30-50/100 Normal   OK   OK   N/A   N/A   OK   OK   OK   OK   OK   OK   OK   O
<ul> <li>36 Any cracking which exceeds normal settlement cracks.</li> <li>37 Moisture reading behind shower recess walls</li> <li>38 Any evidence of significant moisture barrier issues in the plaster.</li> <li>Internal Floors</li> <li>39 Cracks to ground slabs exceeding normal limitations.</li> <li>40 Condition of timber floor boards (if applicable)</li> <li>41 Sufficient access panels available to sub floors (if applicable)</li> <li>Roof Space</li> <li>42 Any significant gaps between structural members due to sagging.</li> <li>43 Unsound modifications done to roof/load bearing walls removed.</li> <li>44 Lateral shift in hangers or strutting beams.</li> <li>45 Sagging to any major roof beams, struts or purlins.</li> </ul>	R   30-50/100 Normal   OK   OK   N/A   N/A   OK   OK   OK   OK   OK   OK   OK   O

# **Additional PrePurchase Items**

### **Electrical**

External

Note; This PrePurchase inspection is not a substitute for a safety inspection by a licensed electrician. Items identified by your inspector are advisory only, a technical assessment by a licensed electrician may uncover additional issues that can not be reasonably identified by a registered building inspector.

48	Unsafe exposed wiring to external walls below 2.4m	OK
49	Orange conduit used above ground unpainted exposed to UV light.	OK
50	External wall lights correctly functioning and properly installed.  Some sensor lights can only be switched on at night time due to built in light sensors in this event the sensor light may not be properly tested during the inspection.	OK
51	Garage sectional door opening and closing properly.  Flat batteries to remotes may limit testing of this item.	OK
	ernal	
52	Light switches in good condition and functioning throughout.	OK
53	Light globes missing or blown during inspection.  The following rooms contained missing or blown light globes, therefore, these lights were not properly tested during the inspection.  none	R
		_
54	GPOs in good condition and correctly fixed to walls.	OK
55	Wet area exhaust fans working properly.	OK
56	Exposed wiring below 2.4m inside the home.	OK
57	Ceiling fans functioning correctly.	OK
	of space Loose wiring present in the roof space causing safety concern.	OK
59	Single insulated lengths of wiring present in the roof space causing safety hazard.	OK
60	Heat shields present over low voltage down lights. (if applicable)	N/A
61	Any obvious evidence of electrical extensions by uncertified individuals which may require safety testing by an electrician?	OK
ΡI	umbing	
	Gas connected and available to site	OK
63	Taps functioning correctly and easy to turn.	OK
64	Shower roses in good condition and functioning.	OK
65	Toilet flushing correctly, cisterns refilling without running continuously.	ОК

66 Leaks present to wastes beneath sinks/ basins/ troughs.	OK
67 Significant blockages to basin/ sink wastes.	OK
Appliances 68 Oven functioning.  Oven will be turned on and considered to be functioning if heat is being produced.  Older gas ovens can be difficult to light, in this instance the oven may not be properly tested and a notation will indicate this in the summary of this report.	ОК
69 Hotplate functioning. All burners will be tested and will be considered functional if heat is being produced.	OK
70 Air conditioner functioning.  The air conditioner will be tested for basic function only. A detailed inspection of the functions is not included as a part of a PrePurchase inspection. If required this must be carried out by an air conditioner technician. Air conditioning may not be tested if remotes are not present or batteries are flat during the inspection.	R
71 HWU working and in good condition. Check base of unit for corrosion	OK
72 Kitchen range hood functioning.	ОК
<ul> <li>72 Kitchen range hood functioning.</li> <li>Water Bodies</li> <li>73 Fencing to water bodies compliant with safety recommendations.</li> </ul>	OK OK
Water Bodies	
Water Bodies 73 Fencing to water bodies compliant with safety recommendations.	ОК
<ul><li>Water Bodies</li><li>73 Fencing to water bodies compliant with safety recommendations.</li><li>74 Self closing gates and doors to water body access points.</li></ul>	OK R
<ul> <li>Water Bodies</li> <li>73 Fencing to water bodies compliant with safety recommendations.</li> <li>74 Self closing gates and doors to water body access points.</li> <li>75 Safe header course around swimming pool.</li> </ul>	OK R
<ul> <li>Water Bodies</li> <li>73 Fencing to water bodies compliant with safety recommendations.</li> <li>74 Self closing gates and doors to water body access points.</li> <li>75 Safe header course around swimming pool.</li> <li>76 Unsafe wiring present to pool pump area.</li> </ul>	OK R OK OK
Water Bodies 73 Fencing to water bodies compliant with safety recommendations. 74 Self closing gates and doors to water body access points. 75 Safe header course around swimming pool. 76 Unsafe wiring present to pool pump area. 77 Orange conduit unpainted above ground in pool pump area.  Boundaries	OK R OK OK OK

Note; reticulation, bore pumps, dishwashers, heaters, spa pumps, TV antennas and other appliances or fixtures not included on this list will not be tested as a part of a standard PrePurchase inspection these items require an inspection by specialized technician if necessary. Comments on these items may be volunteered by the inspector. The presence of asbestos may not be noted as a part of a PrePurchase inspection. A separate asbestos inspector may be required to conduct a specialized inspection to assess for any health and safety concerns that may be present on homes built before 1987. The contents of this checklist may be subject to change without notice. Please read the Terms and Conditions on our website for more details.